

Screening Report

Report:	071-75924520-101	Date:	18/12/2013
Client:	The Electrical Safety Council Unit 331 Great Guildford Business Square 30 Great Guildford Street London SE1 0HS		
Product:	Electrical Accessory	ESC Sample Number:	8
Summary:	TÜV SÜD Product Service was commissioned by The Electrical Safety Council to evaluate an Electrical Accessory (see figure 1). The aim of the assessment is to assess the product against the clients Safety Screening Test Plan.		

Summary

The product was of adequate construction and requires some attention to the user instructions. The product failed on markings, terminal and terminations and screws, current carrying parts and connections and also gave twice the rated output current and was deemed to fail its own stated specification.

Figure 1




Assessed by:

oeres

Anna Jeeves Consumer Product Technician

Reviewed by:

Greg Plummer Consumer Product Test Engineer





= Improvements Required



© 2013 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 1 of 6 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



Testing Information				
Testing Laboratory:	TÜV SÜD Product Service			
Location:	Octagon House, Concorde Way, Segensworth North, Fareham, Hampshire,			
	PO15 5RL. UK.			
Client:	The Electrical Safety Council			
ESC Sample Number:	8			
Product Information				
Product Description:	Trailing socket with Integrated USB Ports			
Rated Input Voltage:	250VAC			
Rated Output:	USB – 2 x 5VDC / 500mA			
Protection Class:	Class I			

	Findings			
	Markings/Warnings BS 5733, Clause			
Marking of Product	-Inadequate			
Comments	The product was marked with the model reference, electrical ratings (low voltage / SELV) and applicable standards (BS 1363 / BS 5733). A known manufacture's trademark was present; however there was no information relating to the distributor (on packaging only) and this must be added. The WEEE logo and CE marking were also missing. There was no standard stated to suggest conformity of the USB outputs.			
	There were some brief instructional / safety information provided on the packaging's carded insert which state that the product is suitable for charging items such as MP3 players, mobile phones, and digital cameras; however this was non-specific. The safety information covered the extension as a whole (including surge protection). There were no compatibility warnings directly related to the USB interface.			
Markings/Photo	See last page of reportCE Marking-Yes See See See See See See See See See S			
	External Construction (BS 5733, Clause 13)			
Product Build Quality	Pass -Fail			
Comments	The external construction was of an adequate standard however the mouldings were considered to be of a lesser quality compared to similar products already on the market. No sharp edges, burrs or pinch points were found.			
	Accessibility of Live Parts			
(BS 5733, Clause 8)				
Constructional Quality	Pass -Fail			
Comments	The casings had been adequately secured with rivets. Access to internal live parts could not be achieved when applying a 1.0mm calibrated test pin to potential areas of access.			




	Terminals & Terminations
	(BS 5733, Clause 14)
Constructional Quality	Pass -Fail
Comments	The product was fitted with an approved 13A, BS 1363 plug and a BS 6500 marked (superseded by BS EN 50525) 3*1.25mm supply cord, both parts were registered to a known manufacturer. It was noted that the cord measured at 1.87M, not 2.0M as stated on the packaging. A quick check revealed that some resistance was felt when an approved BS
	1363 plug was inserted into the socket.
	Internal Wiring / Separation
	(BS EN 61558-1, Clause 21)
Constructional Quality	Pass -Fail
Comments	The output (SELV) circuit was found to be adequately separated from the input circuit. The Live parts of the SELV circuit were not in contact or exposed to the earth.
	Screws, Current Carrying Parts & Connections (BS 5733, Clause 14 & 15)
Constructional Quality	
Comments	The connections to the both the control and surge circuits had been mechanically secured / soldered. The input connections to the conductor strip was found to be suitably retained by crimping; however this method had not been employed to any of the other conductor connections, these were soldered only. It is recommended that two forms of security are used.
	page Distances, Clearances & Distances Through Insulation (BS EN 61558-1, Clause 26)
Constructional Quality	-Pass X-Fail
Comments	The minimum clearance distance measured between the primary and secondary sides of the circuit board (4.4mm) was close to the limit required by the standard (>5mm). The transformer was adequately constructed with a triple insulated secondary winding, providing an adequate barrier from the primary side.

© 2013 Not to be reproduced except in full without the permission of TÜV SÜD Product Service Page 3 of 6 The findings expressed in this report are our considered opinions and are based on our assessment of the samples and / or documentation supplied to us at the time of the assessment. A full or further investigation of the product and / or documentation may result in additional findings.



Short Circuit, Overload and Thermal Protection (BS EN 61558-1, Clause 15) Constructional Quality Image: Pass Image: Pail Comments A cartridge fuse was fitted to the primary side of the control circuit. A thermal protection device was also found on the surge protection circuit. The VDE marking seen was verified online.	
Constructional QualityImage: Pass Image: Pass Ima	
Quality A cartridge fuse was fitted to the primary side of the control circuit. A thermal protection device was also found on the surge protection circuit.	
CommentsA cartridge fuse was fitted to the primary side of the control circuit. A thermal protection device was also found on the surge protection circuit.	
thermal protection device was also found on the surge protection circuit.	
Mechanical Strength	
(BS 5733, Clause 21)	
Result	
Comments The product was subjected to an impact test. This was carried out with the	
free end of the cable held against a wall with the cable held horizontally at	
400mm above a hard floor then allowed to drop. This was repeated with	
the cord rotated through 45° at its fixing eight times. No damage was	
observed.	
observed.	
Standard USB connectors were placed into each socket then subjected to	
an impact test of 5Nm to all sides. Some deformation of the sockets metal	
casing was noted; however this did not affect the mechanical fit of a USB	
plug.	
Insulation Resistance / Leakage Current	
(BS EN 61558-1, Clause 18.2)	
Result — Pass — Fail	
Comments The product was subjected to an insulation resistance test with a voltage of	t
500VDC applied. This was measured between live / neutral and the USB	
output. A measurement of >999M Ω was recorded across each path;	
therefore meeting the requirement of $>5M\Omega$.	
Electric Strength	
(BS 5733, Clause 19 / BS EN 61558-1, Clause 18)	
Result	
Comments The product as a whole was subjected to an electric strength test to	
2121VDC. The output was tested to 4242VDC. No breakdown or flashover	
occurred.	
Output Voltage & Current Under Load	
(BS EN 62684, Clause 5)	
Result	
Comments The device was plugged in and the open circuit voltage measured across	
the USB ground and supply. It was found to be 4.89VDC for either socket	
and was between the limits of 4.75 – 5.25VDC.	
The stated output current was 500mA for each USB socket which is below	
the required limit of 1500mA. Under short circuit conditions both USB	
sockets gave an output current of <50mA at <50mV. The drop in output	
appeared to be caused by some current limiting device. The device gave	
	4
approximately 1A from each channel before the limiting circuit was enable	u
which is twice the stated output.	
The device was setup with a load bank and the load slowly increased until	
the voltage output dropped significantly. The load was then backed off unt	П
the voltage remained stable at a current of approximately 1A on both USB	








Product Images

Internal Overview (Main Assembly)



Markings

Control PCB







Plug



Fuse





Warnings